

SKF Automotive Bearing Grease

LGMT 3

SKF LGMT 3 is mineral oil based, lithium soap thickened grease. This premium quality, general purpose grease is suitable for a wide range of industrial and automotive applications requiring stiff grease.

SKF LGMT 3 is the most widely used grease suitable for car, bus, truck and trailer wheel bearings.

- Excellent rust inhibiting properties
- High oxidation stability within its recommended temperature range
- Good mechanical stability
- Suitable for applications running at continuous ambient temperatures > 35 °C
- Can withstand high operating temperatures of continuous +120 °C
- Dropping point > 180 °C



Available pack sizes

Packsize	Designation
420 ml cartridge	LGMT 3/0,4
0,5 kg can	LGMT 3/0.5
1 kg can	LGMT 3/1
5 kg can	LGMT 3/5
18 kg pail	LGMT 3/18
50 kg drum	LGMT 3/50
180 kg drum	LGMT 3/180




Technical data

Designation	LGMT 3/(pack size)		
DIN 51825 code	K3K-30	Corrosion protection	
NLGI consistency class	3	Emcor: – standard ISO 11007	0–0
Thickener	Lithium	– water washout test	0–0
Colour	Amber	Water resistance	
Base oil type	Mineral	DIN 51 807/1,	
Operating temperature range	–30 to +120 °C	3 hrs at 90 °C	2 max.
	(–20 to +250 °F)	Oil separation	
Dropping point DIN ISO 2176	>180 °C (>355 °F)	DIN 51 817,	
		7 days at 40 °C, static, %	1–3
Base oil viscosity		Lubrication ability	
40 °C, mm ² /s	125	R2F,	
100 °C, mm ² /s	12	running test B at 120 °C	Pass
Penetration DIN ISO 2137		Copper corrosion	
60 strokes, 10 ⁻¹ mm	220–250	DIN 51 811	2 max. at 130 °C (265 °F)
100 000 strokes, 10 ⁻¹ mm	280 max.	Rolling bearing grease life	
Mechanical stability		R0F test	1 000 min. at 130 °C
Roll stability, 50 hrs at 80 °C, 10 ⁻¹ mm	295 max.	L ₅₀ life at 10 000 r/min., hrs	(265 °F)
V2F test	'M'		


Be aware of fake SKF Grease



Warning: The grease inside the fake LGMT 3/1 can, tested in the SKF laboratory, does not meet SKF specifications of LGMT 3 grease and is not suitable for truck wheel bearing application since it increases dramatically a chance of early and sudden bearing failure and can consequently lead to a road accident.



Very low mechanical stability of the fake grease means grease leakage and lubricant starvation causing early bearing failure and consequently increasing a risk of road accident.



Low viscosity of the fake grease (below the required value of 110 mm²/s) means a low wear protection causing early bearing failure and consequently increasing a risk of road accident.



Genuine SKF LGMT 3 Grease Can

skf.com | mapro.skf.com | skf.com/lubrication

© SKF is a registered trademark of the SKF Group.

© SKF Group 2017

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

Certain image(s) used under license from Shutterstock.com.